Oil Field Environmental Incident Summary

Incident: 20151209131947 **Date/Time of Notice:** 12/09/2015 13:19 Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC OASIS PETROLEUM NORTH AMERICA LLC Well Name: KELTER 7-1H2 Field Name: EIGHTMILE Well File #: 26000 Facility ID Number: **MCKENZIE** Twp: 152 Rna: 102 Sec: 7 County: Location Description: Submitted By: Tony Novak Received By: Contact Person: Tony Novak 1001 FANNIN STE 1500 HOUSTON, TX 77002 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Truck Overflow Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown Units Recovered Units Spilled Followup **Units** Oil **Brine Barrels** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: soil Areal Extent:

Potential Environmental Impacts:

soil

Action Taken or Planned:

oncall has been notified so we can begin clean up process....

Wastes Disposal Location: nuverra environmenta soulotions terrefficient

Agencies Involved:

Updates

Date: 12/9/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on the facility site according to the report. NDIC retains oversight.